

Infiniti Q50 touch screen doesn't work

With the democratization of new technologies, the intensive use of smartphones, 24-hour internet connection and internet sites, it was obvious that cars would stick to the phenomena. And after the era of the DVD car radio that could be added to the Infiniti Q50, for a few years now many cars have been equipped with touch screens. Nevertheless this provides a specific comfort, with technology comes also the problems. In this article we're going to try to help you fix a touch screen issue that doesn't work on Infiniti Q50 anymore. To get this done, to begin with, we're going to see the pros of having a touch screen in your car, then the various touch screen complications on Infiniti Q50 , and at last how to correct them.



Benefits of a touch screen on Infiniti Q50

Before we can find out why the touch screen of your Infiniti Q50 no longer functions, we will first see all the positive points that this equipment will provide you. We will only concentrate on the native touch screens, those in the

One of the reasons an Infinite Q50 radio might be working is a blown fuse or a bad electrical connection. If there has been any recent impact on the car, the radio wire might have come loose. This can be troubleshooted by taking out the radio unit and checking the wires connecting to it. If the main wire is out of the socket, then plug it back in and try again. If there is no sign of life or disconnections, then it might be a bad fuse in the fuse box. That might be a little harder to diagnose for a non-pro. Before taking the car in for a tech to look at it, first try to reset the radio itself. Usually by holding down the power button for a few seconds and releasing it.

Bart August 16, 2022

Press the big button on the steering wheel on the right side. Then use the silver "set" button with a plus and minus sign to set it (down to set) and then use the plus and minus key to increase or decrease your speed—braking will turn it off.

Willie B July 30, 2020

The 2019 INFINITI Q50 radio may stop working due to bad wiring, a blown fuse, or amp problem

The Questions and Answers on this page are the statements and opinions of their respective authors and not VehicleHistory.com. VehicleHistory.com does not research or authenticate any of the Answers provided.